

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-3213	DATE	14.05.2021
MANUFACTURER	Ferrari SpA (Japanese Importer: Ferrari Japan K.K.)		
DESCRIPTION OF DEFECT	Due to the improper voltage threshold of the electrical actuator firmware for the exhaust bypass valve, there is a possibility that the check engine lamp will illuminate and the engine power is controlled to decrease by the fail safe mode in worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-F164BCA	Portofino	2018-2019	148
		TOTAL	148