

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

| | | | |
|-----------------------|---|-----------------------------------|-------------------|
| CAMPAIGN NO. | 4 9 5 4 | DATE | May. 14. 2021 |
| MANUFACTURER | NICHIGO CORPORATION | | |
| DESCRIPTION OF DEFECT | <p>①In electrical wiring of rotary snowplow, Due to improper wiring, Some covers and electrical wiring are in contact. The coating of electrical wiring may be damaged by running vibration. Therefore, a short circuit may occur at the damaged part and burn out, and in the worst case, a fire may occur.</p> <p>②In electrical wiring of rotary snowplow, Due to improper wiring, The starter motor wiring and ground wiring may come into contact. The coating of electrical wiring may be damaged by running vibration. Therefore, a short circuit may occur at the damaged part and burn out, and in the worst case, a fire may occur.</p> | | |
| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
| YDR-R08E | 「HTR148」 | 2018~2021 R08E-0002~ R08E-0048 | ① 45 ② - |
| YDR-R09E | 「KBR108」 | 2017~2021 R09E-0002~ R09E-0060 | ① 53 ② 57 |
| YDR-R10E | 「HTR88」 | 2017~2021 R10E-0002~ R10E-0093 | ① 87 ② 90 |
| | | TOTAL | ① 185 ② 147 |

【Notes】 The scope of the chassis number of the recalled vehicles, there is a case where