

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3214	DATE	May 18, 2021
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	When the seat belt is unfastened, the visual display disappears again after a short time and the acoustic seat belt warning is only issued once in the instrument cluster due to improper program of the control unit.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-4MDCBS	Audi Q7 55Tq	2021	1
3AA-8WDDWA	Audi A4 allroad	2020	51
3AA-8WDDWF	Audi A4 45Tq	2020	229
3AA-8WDEM	Audi A4 35T	2020	398
3AA-F2DKML	Audi S6	2021	1
3AA-F5DDWL	Audi A5 SB 45Tq	2021	3
3AA-F8CWWF	Audi S8	2021	4
3AA-F8CXFY	Audi A8 60Tq	2021	1
3AA-F8CZSF	Audi A8 55Tq	2021	3
3BA-8WCWGF	Audi S4	2020	102
3BA-8WDECF	Audi RS4 Avant	2020-2021	36
ABA-4MCYRA	Audi Q7 45Tq Air- suspension	2021	1
		Total	830