

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3219	DATE	May. 20. 2021
MANUFACTURER	Thai Honda Manufacturing Co., Ltd.		
DESCRIPTION OF DEFECT	Rear reflector may have internal surface molded into incomplete form due to inadequate control over reflector molding conditions. Such a reflector can bring about scattering of reflected light, thereby not complying with Article 38 (Standards for Rear Reflectors) of the Safety Regulations for Road Vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BK-MD49	「Rebel 250」	2020-2021	14,569
2BJ-JB02	「Monkey125」	2020-2021	4,558
2BK-MD47	「CRF250L」 「CRF250 RALLY」	2020-2021	2,457
2BJ-JC75	「GROM」	2020	2,136
2BJ-JA48	「Super Cub C125」	2020-2021	2,109
2BJ-JC92	「GROM」	2020-2021	1,121
2BK-MD44	「CRF250L」 「CRF250 RALLY」	2020	958
TOTAL			27,908