

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4957	DATE	May 27,2021
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to improper installation of the earth bolt of the lithium-ion battery, poor connection to the ground may occur. If the vehicle continues to be used in this condition, the engine may not restart after the AS&G auto-stop operates, and/or the engine may not stop, which may lead to thermal incident.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5AA-B34A	「eK SPACE」	2020	3,089
4AA-B35A		2020	1,911
5AA-B37A		2020	883
4AA-B38A		2020	657
5AA-B44A	「ROOX」	2020	9,691
4AA-B45A		2020	4,770
5AA-B47A		2020	1,585
4AA-B48A		2020	669
		TOTAL	23,255