VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3224	DATE	2021/6/3	
MANUFACTURE	Mercedes-Benz AG			
	(Japanese Importer : Mercedes	(Japanese Importer : Mercedes-Benz Japan Co,. Ltd.)		
DESCRIPTION OF	On certain GLE and (167 platform) the air conditioning drain hoses might be incorrectly fitted			
DEFECT	in the vehicle. In this case, condensation water from the air conditioning might enter the			
	passenger compartment.			
	If condensation water enters into the driver and passenger side footwells, it might cause			
	corrosion and/or short circuits to the electrical components installed in this area.			
	This condition would increase the risk of fire due to a short circuit. In addition, the			
	performance of other features of the vehicle could be impacted such as the automatic			
	emergency call (eCall) might not be available, the vehicle might not be able to be unlocked			
	and/or started and the engine limp-home mode might be activated during driving.			
	This increases the potential risk of injury or a crash.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
3DA-167119C	GLE300d 4MATIC	2019	108
3DA-107119C		2020	2
3DA-167123	GLE400d 4MATIC	2019	346
EAA 1471EO	GLE450 4MATIC		291
5AA-167159		2020 11 9	1
4AA-167161	Mercedes-AMG GLE53 4MATIC+		4
3DA-167923	GLS400d 4MATIC		11
4AA-167986	GLS580 4MATIC		9
		TOTAL	772