VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3228	DATE	2021/6/3		
MANUFACTURE	Mercedes-Benz AG				
	(Japanese Importer : Mercedes-Benz Japan Co,. Ltd.)				
DESCRIPTION OF DEFECT	(Japanese Importer: Mercedes-Benz Japan Co,. Ltd.) On certain GLE (167 platform) with 6-cylinder gasoline-engine (M256) the ignition coils or their installation might not meet specifications. Subsequently, a permanent failure of the ignition spark might occur, which would lead to misfiring on the affected cylinder. In this case, a limp home mode with reduced engine power would be activated and the malfunction indicator light (MIL) would be illuminated. Local legal requirements regarding exhaust emission values might not be met.				

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
5AA-167159	GLE450 4MATIC	2020	7
4AA-167161	Mercedes-AMG GLE53 4MATIC+		3
4AA-167361	Mercedes-AMG GLE53 4MATIC+		10
	Coupe		
		TOTAL	20