

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 9 7 1	DATE	Jun. 10. 2021
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Regarding the body control module, the passing beam, which should be continuously turned on in conjunction with the adapted front lighting, turns off due to improper control program if the light switch is operated to the small position with adaptive front lighting and fog lamps turned on. Therefore, it does not comply with safety regulation for headlight.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
6AA-E13	N I S S A N N O T E	2 0 2 0 ~ 2 0 2 1	11,317
		TOTAL	11,317