

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4976	DATE	June 18, 2021
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	<p>①Due to inappropriate pin selection of the power transmission devices, the pin that connects the main shift lever to the driving HST may come off by getting caught on straw. Therefore, the vehicle may not stop unless the ignition key is turned off in the worst case.</p> <p>②Due to inappropriate pin selection of the brake rod, the pin that connects the brake pedal and parking brake arm may come off by getting caught on straw. Therefore, parking brake doesn't work any more by a parking brake pedal.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
C229	-	①②2007~2014	①②6,560
		①②2013~2021	①2,247 ②2,254
		①②2018~2021	①145 ②146
C230	-	①②2007~2014	①②5,974
		①②2013~2021	①2,345 ②2,360
		①②2018~2021	①135 ②138
		TOTAL	17,432