

Form No. 4: Summary of Recall Campaign in English (Related to Article 2)**Vehicle Safety/Pollution Recall Campaign in Japan**

Import Vehicles

Campaign No.	Gai-3240	Date	June. 22, 2021
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	Right hand front seat belt assemblies have been manufactured away from specification. One of the mechanical sensor devices in the seat belt assembly, the Car Sensor device, has a plastic moulded part which is not fully formed. In this condition the seat belt may not function as required. Inspect the front right seatbelt assembly and renew if required.		

Type	Commercial name	Model year recalled	Number of vehicles
3CA-LZ2NB	Range Rover Evoque	2021	2
Total			2

(JIS A4 size)