

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/ Import Vehicles

CAMPAIGN No.	4973	DATE	25 Jun, 2021
MANUFACTURER	MITSUBISHI MAHINDRA AGRICULTURAL MACHINERY CO.,LTD.		
DESCRIPTION OF DEFECT	<p>In a harvesting and threshing truck (= combine harvester), the exhaust pipe and its vicinity are inappropriately insulated, and also straw debris accumulated near the exhaust pipe due to design issue.</p> <p>So the surface temperature of the exhaust pipe rises during Diesel Particulate Filter (DPF) regeneration process and heated exhaust pipe comes into contact with accumulated debris, which may cause smoke generation and, in the worst case, ignition, leading to a vehicle fire.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
WDR-VC12B	「V6120」	2015,2016,2017	58
		TOTAL	58