

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4980	DATE	July 1, 2021
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the driver's air bag, due to improper material of the brand emblem on the air bag module cover, the brand emblem may hydrolyze, causing deterioration in itself. Accordingly, the emblem may break apart and become projectile during air bag deployment, causing injury to occupants.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UA-BK5P	Mazda 「Axela」	2003-2004	6,880
DBA-BK5P DBA-BK5P KAI		2004-2006	33,334
UA-BKEP		2003-2004	9,195
CBA-BKEP		2004-2006	11,000
DBA-BKEP		2006	1,219
UA-BK3P		2003-2004	7,455
CBA-BK3P		2004-2006	4,806
DBA-BK3P		2006	342
			Total