

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	Gai-3242	Date	7-Jul-21
Manufacture	CATERPILLAR JAPAN LLC.		
Description of Deffect	An internal bearing in Hydraulic pump may damage and separate. The separated piece can prevent the intended hydraulic power train cotrol. Then, the travel performance can be obstacled.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDP-H22	「910M」	2019, 2020	275
YDP-H24	「914M」	2020	3
YDR-H26	「918M」	2019, 2020	49
		TOTAL	327