

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3245	DATE	2021/7/8
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain CLA (118 platform), C-Class (205 platform), GLC (253 platform) and G-Class (463 platform) vehicles with gasoline-engine the ignition coils might not meet specifications. In this case a reduction of the ignition coils performance might occur, which would lead to misfiring on the affected cylinder. Subsequently, the engine would run rough with reduced power. The malfunction indicator light (MIL) would be illuminated. Local legal requirements regarding exhaust emission values might not be met.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
4BA-118654M	Mercedes-AMG CLA45S 4MATIC+ Shooting Brake	2021	1
4BA-205364C	Mercedes-AMG C43 4MATIC Coupe		2
4BA-205464C	Mercedes-AMG C43 4MATIC Cabriolet		1
4BA-253964	Mercedes-AMG GLC43 4MATIC		12
4BA-253364	Mercedes-AMG GLC43 4MATIC Coupe		9
3BA-463276	Mercedes-AMG G63		9
		TOTAL	34