

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3246	DATE	2021/7/8
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain GLB vehicles (247 platform) the vehicle body might not be sealed according to specifications in the area of the front wheel wells.</p> <p>In this case, water might enter from the wheel wells into the front foot wells. This might impair the functions of control units and other electric components installed in these areas. Among others, the instrument cluster might malfunction and not show any information. Furthermore, the engine might stall during driving or might not start.</p> <p>In consequence, the risk of a crash might increase.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-247612M	GLB200d	2020	16
5BA-247647M	GLB250 4MATIC		18
		TOTAL	34