

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-3253	DATE	July 15, 2021
MANUFACTURER	KTM AG (Japanese Importer : KTM Japan KK)		
DESCRIPTION OF DEFECT	The preload force of the return spring may, in individual cases, lie outside the specified tolerance. This can result in the brake piston not being returned to its original position, which in rare cases can impair the function of the front brake. For this reason, the return spring must be replaced on affected vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
790ADVTS347	790 Adventure	From 2019 to 2020	223 UNITS
790ADVTR347	790 Adventure R	From 2019 to 2020	62 UNITS
2BL-790DUKE	790 Adv	From 2019 to 2020	69 UNITS
2BL-790DUKE	790 Adv R	2020	87 UNITS
		TOTAL	441 UNITS