

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3256	DATE	July 16th, 2021
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	During vehicle assembly the fuel line may not have been installed according to specifications. It may be possible for the fuel line to chafe on the clean air pipe or the engine cover. In the worst case this could lead to a small fuel leakage over time.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-XN15	MINI Cooper D	2016 - 2018	1,166
LDA-XN15M	MINI Cooper D	2018 - 2020	2,051
3DA-XY15MW	MINI Cooper D	2020	213
LDA-LR20	MINI Cooper D Clubman	2016 - 2019	6,694
	MINI Cooper SD Clubman		3,887
3DA-BB20M	MINI Cooper D Clubman	2019 - 2020	854
	MINI Cooper SD Clubman		377
LDA-XT15	MINI Cooper D 5 Door	2016 - 2018	4,196
LDA-XT15M	MINI Cooper D 5 Door	2018 - 2020	4,068
3DA-XV15MW	MINI Cooper D 5 Door	2020	359
LDA-XN20	MINI Cooper SD	2016 - 2018	1,730
LDA-XN20M	MINI Cooper SD	2018 - 2020	1,314
3DA-XY20MW	MINI Cooper SD	2020	66
LDA-XT20	MINI Cooper SD 5 Door	2016 - 2018	2,056
LDA-XT20M	MINI Cooper SD 5 Door	2018 - 2020	2,038
3DA-XV20MW	MINI Cooper SD 5 Door	2020	103
TOTAL			31,172