

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 3258	DATE	21 July, 2021
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	Due to an internal software error in the high-voltage power electronics, it is possible for the affected vehicles to display the warning message "Drive control disturbed - Park vehicle safely" in the instrument cluster.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-J1MB	Taycan 4S	2021	264
ZAA-J1MC	Taycan Turbo	2021	66
ZAA-J1MD	Taycan Turbo S	2021	89
ZAA-J1NA1	Taycan	2021	19
ZAA-J1NA1C	Taycan	2021	46
		Total	484