

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

| | | | |
|-----------------------|--|------|-----------------|
| CAMPAIGN No. | Gai-3254 | DATE | 26 / July /2021 |
| MANUFACTURER | Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited) | | |
| DESCRIPTION OF DEFECT | Volvo Cars quality investigations have identified that there may be a risk where the 15A fuse could blow. A blown fuse will prevent the low-pressure fuel pump to operate. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-------|-----------------------|---------------------|-------------------|
| VOLVO | [S60] | 2020 | 1,213 |
| VOLVO | [V60] | 2019-2020 | 1,527 |
| VOLVO | [V60 Cross Country] | 2019-2020 | 1,256 |
| VOLVO | [V90] | 2019-2020 | 103 |
| VOLVO | [V90 Cross Country] | 2019-2020 | 65 |
| VOLVO | [XC60] | 2019-2020 | 965 |
| VOLVO | [XC90] | 2019-2020 | 333 |
| | | TOTAL | 5,462 |