

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3261	DATE	July 29, 2021
MANUFACTURER	Bentley Motors Limited (Japanese Importer : Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	For the fuse board and the harness installed behind the driver's footwell A post trim cover, the trim cover could be pushed from the inner side due to inappropriate installation of these parts. Consequently, the A post trim cover which is pushed from the inner side will contact the accelerator pedal, in the worst case, the accelerator pedal may not return from depressed position.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-BCDDB	Continental GT	2018 - 2021	186
7BA-BCCVD	Continental GT V8	2020 – 2021	37
7BA-BDDDB	Continental GT Convertible	2019 – 2020	32
7BA-BDCVD	Continental GT V8 Convertible	2020 – 2021	10
7BA-BBDDDB	Flying Spur W12	2020 – 2021	60
7BA-BBCVD	Flying Spur V8	2021	2