

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4997	DATE	Jul. 30. 2021
MANUFACTURER	Kawasaki Heavy Industries, Ltd.		
DESCRIPTION OF DEFECT	<p style="text-align: center;">The amount of grease applied to the needle-bearings in the rear hub housing may be insufficient due to variations in the application process. With continuous use, this could lead to bearing failure, in the worst case causing the rear wheel to lock.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Notes
2BL-ZXT02A	「Ninja H2 SX」 「Ninja H2 SX SE」 「Ninja H2 SX SE+」	2018～2020	2,178	
TOTAL			2,178	