

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4998	DATE	Jul. 30. 2021
MANUFACTURER	Kawasaki Heavy Industries, Ltd.		
DESCRIPTION OF DEFECT	<p>On eligible units, the components of the relief valve that adjusts the oil pressure of the engine may come off due to improper assembly. When the oil pressure warning indicator is turned on, the engine becomes poorly lubricated. In the worst case, the engine may stop.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Notes
2BL-ZRT00K	Z H2 Z H2 SE	2020~2021	624	
2BL-ZXT02J	Ninja H2 CARBON	2021	25	
8BL-ZXT02L	Ninja ZX-10R Ninja ZX-10RR	2021	77	
<b>TOTAL</b>			<b>726</b>	