

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	gai-3236	DATE	July 6th, 2021
MANUFACTURER	DUCATI MOTOR HOLDING SpA (Japanese Importer: DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	A possible problem to the side stand. In particular, when the motorcycle is placed on the side stand, it may happen in some rare cases that it breaks at the welding joint of the tube of the stand itself and the forged upper part. In exceptional situations, it breaks, causing the motorcycle to fall.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-AC00	MULTISTRADA 1260 S, MULTISTRADA 1260 PIKES PEAK	2018	44
		TOTAL	44