VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 3264	DATE	3 August, 2021
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG		
	(Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	Due to a process error during production, there is a		
	possibility that the threaded connection securing the		
	steering column to the steering gear does not meet the		
	required specifications on the affected vehicles.		
	If this is the case, the steering column can become detached		
	from the steering gear over the service life of the vehicle. As		
	a result, we cannot	rule out the poss	sibility that the steering
	will fail.		

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
ABA-E3K29	Cayenne S	2019	1
		Total	1