

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3263	DATE	2021/8/5
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	On certain V-Class vehicles (447 platform) the middle fastening of the roof rail could come loose. If the fastening of the screwed connection of the middle fastening on the roof rail would become loose, the secure fixing of the roof load cannot be permanently ensured. In a worst case scenario, a detachment of the roof load during driving or in case of a crash cannot be ruled out. This could increase the potential risk of a crash and injury to a third party.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-447811C	V220d	2021	4
		TOTAL	4