

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5006	DATE	August 20, 2021
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	<p>In the parking brake of the shovel loader, since the assembly process is inappropriate, the yoke interferes with the lever when assembling the hydraulic cylinder end yoke and the parking brake lever, there is a case that damage the plate inside the parking brake. Therefore, when repeating the operation and release of the parking brake in the as-is state, the crack is developed from the damaged portion of the plate, in the worst case, there is a possibility that the plate cannot hold the vehicle in a stopped state broken.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDP-WA138	「WA150-8」	2019-2021	145
YDP-WR005	「WR12-8」	2020-2021	1
TOTAL			146