

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5000	DATE	Aug.26 2021
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	In the wheel crane retarder, the nuts that secure the flange connecting with the propeller shaft may be incompletely crimped. Therefore, if using as it is, the nuts and flange may fall off and power may not be transmitted. In the worst case, the retarder may be damaged or damaged parts may fall on the road and interfere with other traffics.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
YDS-KRC016	KR-50H	2016~2018	466	
YDS-KRC017	KR-25H	2016~2018	440	
TOTAL			906	