

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5002	DATE	Aug. 26 2021
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty trucks (4-axle vehicles) with air suspension, the length of the tandem propeller shaft (propeller shaft between the rear front axle and the rear rear axle) is improperly set, so the spline shaft pushes the plug when the tandem propeller shaft contracts the most. As a result, the plug may fall off and affect other traffic.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FS74GY	「FUSO SUPER GREAT」	2017~2020	14
2PG-FS74GZ		2017~2021	350
2PG-FS74HY		2017~2021	175
2PG-FS74HZ		2017~2021	10,990
2PG-FS75GY		2017~2020	5
2PG-FS75GZ		2017~2020	53
2PG-FS75HY		2019~2020	5
2PG-FS75HZ		2017~2021	1,529
		TOTAL	13,121