

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3273	DATE	August 26th, 2021
MANUFACTURE	McLaren Automotive (Japanese Importer : McLaren Automotive Asia Pte Ltd.)		
DESCRIPTION OF DEFECT	Because of improper manufacture management of banjo bolt on the brake caliper, the covered vehicles may have been fitted with an incorrectly manufactured banjo bolt which does not have a hole for brake oil to bypass. This would cause no hydraulic pressure to the brake caliper and could result in the brake may not work.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7BA-P22GT	McLaren GT	2020	1
		TOTAL	1