

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5009	DATE	Sep.3,2021
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	<p>On some wheel cranes, due to the inappropriate design of the hydraulic suspension circuit of the suspension system, abnormal high pressure may be generated in the suspension cylinder of the front axle when the crane rides up a step in the suspension lock state in the moving posture in the crane premises. Therefore, if the crane is continued to be used in the same condition, the front axle suspension cylinder may be damaged, the hydraulic oil in the cylinder may leak, and the crane may become unable to travel.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
YDS-T016	「GR-600N-3」	2019-2021	219
		TOTAL	219