

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5012	DATE	Sep. 7 2021
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy and medium-duty trucks, locknuts for front axle hub bearings were improperly manufactured, and locknuts with larger effective thread diameters were installed at the time of manufacture. Therefore, the threads of these locknuts may be damaged during use, and in the worst case, wheels may come off together with the hub drum.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FK62FY	「FUSO FIGHTER」	2021~2021	9
2KG-FK62FZ		2021~2021	32
2KG-FK65FY		2021~2021	12
2KG-FK65FZ		2021~2021	13
2KG-FK72FY		2021~2021	6
2KG-FK72FZ		2021~2021	14
2PG-FS70HZ	「FUSO SUPER GREAT」	2021~2021	3
2PG-FS74GZ		2021	1
2PG-FS74HZ		2021~2021	59
2PG-FS75HZ		2021~2021	12
		TOTAL	161