VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	gai — 3268	DATE	September 7th, 2021
MANUFACTURER	DUCATI MOTOR HOLDING SpA		
	(Japanese Importer: DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	The engine valve guides may experience excessive wear and can generate abnormal noise. It also may lead to the mechanical breakage of the valve head in the concerned cylinder if continuously use it as it is. Therefore, the engine will no longer be able to deliver the intended power output, and this could lead to potentially dangerous situations. As a result, acceleration and performance may be reduced, thus not meeting the rider's expectations and increasing the risk of crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-1A00	Multistrada V4 S	2021	16
		TOTAL	16