

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3280	DATE	September 9, 2021
MANUFACTURE	General Motors Company (Japanese Importer : General Motors Japan Ltd.)		
DESCRIPTION OF DEFECT	General Motors has decided that a defect, which relates to motor vehicle safety, exists in certain 2020 to 2022 model year Cadillac CT4 and CT5 vehicles. In rare cases, the roof rail side airbags in these vehicles may not have been installed correctly during vehicle assembly. The roof rail side airbag may have been assembled into the vehicle with a twist between two of the RRAB attachment points. This condition can exist on either the left side or right side of the vehicle. An incorrectly installed airbag may not deploy properly in a crash. If the roof rail side airbag does not deploy properly, there is increased risk of injury in a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
「7BA-A2LL」	「CT5」	2021	134
		TOTAL	134