

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	外 - 3265	DATE	Sept 10 2021
MANUFACTURE	LIEBHERR (Japanese Importer : Liebherr-Japan Co.,LTD.)		
DESCRIPTION OF DEFECT	The unit of speed meter(km/h) on telltale in chassis cabin is not illuminated. Therefore, driver may not notice driving speed unit in the dark, and it has possibility to not comply for Japanese safety regulation for road and vehicles(No.46 Speed meter etc.).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	MK88	2019~2021	4 units
Unknown	LTM1075NX	2020~2021	4 units
Unknown	LTM1100NXIII	2020~2021	3 units
Unknown	LTM1120NV	2018	1 unit
Unknown	LTM1120NX-2	2019~2020	4 units
Unknown	LTM1120NZ	2017~2021	56 units
Unknown	LTM1220NX-2	2017	1 unit
Unknown	LTM1250NX	2017~2021	32 units
Unknown	LTM1400NX	2018~2018	2 units
Unknown	LTM1700NX	2021	1 unit
		TOTAL	108 units