

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5014	DATE	Sep.16 2021
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy and medium-duty trucks, the tool used to tighten the rear bumper mounting bolts was improper and the bolts were not tightened to the specified torque. Therefore, the mounting bolts may loosen during use, and in the worst case, the rear bumper may fall off and disturb other traffic.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FV70GX	「FUSO SUPER GREAT」	2021~2021	4
2KG-FV70HX		2021	1
2KG-FV70HXP		2021	1
2PG-FS70HZ		2021~2021	7
2PG-FS74GZ		2021~2021	5
2PG-FS74HY		2021~2021	14
2PG-FS74HZ		2021~2021	113
2PG-FS75HZ		2021~2021	27
2PG-FU74GY		2021	1
2PG-FU74HY		2021~2021	3
2PG-FU74HZ		2021~2021	48
2PG-FU75HZ		2021~2021	24
2PG-FV70GX		2021	1
2PG-FV70GY		2021~2021	2
2PG-FV70HX		2021~2021	29
2PG-FV70HY		2021~2021	10
2PG-FV70HZ		2021~2021	3
2PG-FV74GZ		2021~2021	9
2PG-FV74HZ		2021~2021	10
2PG-FY70HY		2021~2021	3
2PG-FY74GY	2021~2021	2	
2PG-FY74HY	2021~2021	8	
2DG-FQ62F	「FUSO FIGHTER」	2021~2021	14
2KG-FK62F		2021~2021	54
2KG-FK62FY		2021~2021	15
2KG-FK62FZ		2021~2021	50
2KG-FK65F		2021~2021	100
2KG-FK65FY		2021~2021	9
2KG-FK65FZ		2021~2021	37
2KG-FK72F		2021~2021	60
2KG-FK72FY		2021~2021	6
2KG-FK72FZ		2021~2021	14
2KG-FK75F		2021~2021	4

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FK62N	「FUSO FIGHTER」	2021~2021	4
2PG-FK65N		2021	1
2PG-FK65NA		2021~2021	6
2PG-FK72N		2021~2021	27
2PG-FK72NA		2021	1
2PG-FK75N		2021~2021	2
		TOTAL	729