

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3289	Date	September 17, 2021
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	In the brake servo connection rod, the tightening torque at the connection is insufficient due to improper assembly instructions at the time of manufacture. As a result, the bolted connection may loosen completely, and in the worst case, detach from the brake servo connection rod, the brake may no longer functioning.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-3CDPC	Passat sedan 1.5/110kW	MY2021	11
	Passat Variant 1.5/110kW	MY2021	37
3DA-3CDFH	Passat Variant TDI/140kW	MY2021	1
3BA-3HDNUF	Arteon 2.0/200kW	MY2021	38
		Total	87