

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3279	DATE	September 22, 2021
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	Due to a manufacturing process errors, a weld joint in the brake pressure unit may not have been performed correctly. If the weld joint comes loose completely, this could result in the failure of the servo assistance, including the anti-lock brake system (ABS) and electronic stabilization control (ESC) functions under hard braking. In the worst case, the braking distance may be longer.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-GEEAS	Audi e-tron	2020	15
ZAA-GEEASB	Audi e-tron 50	2021	7
		Total	22