

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3287	DATE	2021/9/29
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain E-Class (213 platform), GLC (253 platform), AMG GT 4-doors coupe (290 platform), and G-Class (463 platform) vehicles the locking mechanism for the electrical connector of the side crash sensors might not meet specifications.</p> <p>In this case, it cannot be completely ruled out that the connector of a side crash sensor might loosen over vehicle lifetime. In the event of a crash with side impact, this would lead to a delayed activation of the restraint systems, resulting in a reduced restraint performance. In this case, the risk of injury for occupants would be increased. Furthermore, local legal requirements might not be met.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-253915	GLC220d 4MATIC	2020	12
3DA-253915C			1
3DA-253315	GLC220d 4MATIC Coupe		3
5BA-253984	GLC300 4MATIC		1
4BA-253364	Mercedes-AMG GLC43 4MATIC Coupe		3
7BA-213089	Mercedes-AMG E63S 4MATIC+	2021	4
3DA-463349	G350d	2020	41
3BA-463276	Mercedes-AMG G63		10
4AA-290659	Mercedes-AMG GT43 4MATIC+	2021	2
		TOTAL	77