

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3292	DATE	2021/9/29
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain S-Class (223 platform) vehicles the bolting of the 48V wiring harness on a body-sided support point might not meet specifications.</p> <p>In this case, the electrical connection between the 48V wiring harness and the support point could be sporadically interrupted, which could cause electric arcs. As a consequence, a possible risk of fire could not be completely ruled out.</p> <p>Should the electrical connection be completely interrupted, the vehicle could no longer be started. In this case, local legal requirements in Japan might not be met.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-223033	S400d 4MATIC	2021	3
5AA-223063	S500 4MATIC		1
5AA-223163			5
		TOTAL	9