## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

			,
CAMPAIGN No.	Gai-3293	DATE	September 29, 2021
MANUFACTURE	Automobiles CITROEN (Japanese Importer : Groupe PSA Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	Torque converter was not properly positioned when automatic gear box was tested at test bench after assembly. This caused damage of oil seal inside torque converter and oil leak inside the converter. Customer effects due to this failure are warning light coming on, message appearing on meter cluster and difficulties to change gears. Rectification by the recall is to replace torque converter by new one for all affected vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BA-B6HN05	C3	2021	49
5BA-A8HN05	C3 Aircross	2021	9
	TOTAL		58