

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Imported Vehicles

CAMPAIGN No.	gai-3286	DATE	September 30 , 2021
MANUFACTURER	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	The child safety lock of the rear doors may be unlocked on its own by some vibration because the lock position cannot be maintained due to the inappropriate design reference value of the component parts and leaving the lock position for long time in a hot temperature environment. Under this condition, inner door lever open operation will cause the door to be opened from the inside.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-HEH5F	KADJAR	2017-2018	252
		TOTAL	252