VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3290	Date	September 30, 2021	
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)			
DESCRIPTION OF DEFECT	The arm of the fuel gauge sender in the secondary tank chamber may get stuck on the fuel lines of the suction-jet pump due to inappropriate clearance, As a result, the remaining amount of fuel cannot be detected correctly by the fuel gauge and it may be displayed more than it actually is, and in the worst case, there is a risk of the vehicle cannot be driven due to running out of fuel while driving.			

ТҮРЕ	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
LDA-5NDFGF	Tiguan TDI/110kW	MY2020	257
		Total	257