

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5025	DATE	Oct.7 2021
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	<p>In crane vehicles, fuse boxes may have the wrong fuse insertion positions.</p> <p>Therefore, the specified capacity of the fuse and the rated capacity of the work equipment may not match, and even if the current value of the equipment exceeds the rated capacity, the fuse may not blow and the equipment may be damaged. In the worst case, the equipment may ignite and cause a fire.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
KA4120	—	2019~2020	9	
TOTAL			9	