

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5026	DATE	Oct.7 2021
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	<p>In crane vehicles, the seatbelt take-up device may interfere with the cover behind the driver's cabin and may be pushed up due to improper design of the bracket for attaching the seat, and may contact with the seat cushion.</p> <p>Therefore, excessive force may be applied to the lock portion that fixes the seat cushion, and the lock may be released and the seat cushion portion may fall off.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
KA4120	—	2019~2020	11	
TOTAL			11	