

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5029	DATE	October.13.2021
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the quarter window glass molding mounted at the rear part of the rear door, due to improper mounting structure of the molding, there is a possibility that the molding mounting portion could deteriorate and peel by repeated temperature fluctuations. In this condition, a gap may develop between the molding and the quarter window glass, causing abnormal noise. In the worst case, the molding could detach from the quarter window glass.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
6AA-AZSH20	[CROWN]	2018-2020	32,405	RS grade
6AA-AZSH21			5,184	
6AA-GWS224			4,402	
3BA-ARS220			2,805	
		TOTAL	44,796	