

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5037	DATE	Oct.19,2021
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	On some cranes, the securing bolts may loosen due to inappropriate pad storage support securing methods. In the worst case, the pad storage support and the pads may protrude from the vehicle body while driving, obstructing other traffic.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
YDS-T012	「GR-250N-4」	2017-2021	987
YDS-EE05	「RK250-9」	2018-2021	43
		TOTAL	1030