

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5038	DATE	Oct.19,2021
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	On some transporters, the orange portion of the marker lamp is visible from the rear of the vehicle and therefore does not comply with safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
2RG-XZU720M	HINO 「HINO DUTRO」	2020	2
2KG-XZU720M		2021	1
2RG-XZU722M		2020 - 2021	4
2KG-XZU722M		2020 - 2021	8
2KG-XZU730M		2020 - 2021	4
2RG-XZU722	TOYOTA 「TOYOTA DYNA」 「TOYOA TOYOACE」	2021	1
2KG-XZU722		2020 - 2021	10
2KG-XZU730		2021	1

2PG-FEB50	MITUSBISHI 「CANTER」	2020	1
2RG-FEB50		2021	1
2PG-FEB80		2020 - 2021	12
2PG-FEB90		2021	1
2RG-NPR88AN	ISUZU 「ISUZU ELF」	2020 - 2021	11
2RG-NPR88YN		2021	1
2RG-LPR88AN	MAZDA 「TITAN」	2020	1
		TOTAL	59