

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-3300	DATE	21 / October/ 2021
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	A welding connection in the Hydraulic Unit of the Brake System may be partially, or fully missing. This may lead to no active brake support functions, which will require a higher pedal force and longer pedal travel, resulting in less deceleration than normal.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[V60]	2020-2021	3
VOLVO	[V90]	2021	1
VOLVO	[XC90]	2021	2
		TOTAL	6