

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-3303	DATE	October 21. 2021
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	In the production of the titanium valves, a process deviation occurred in the surface coating of a production lot. The changed surface can result in increased wear of the valve guides over the service life.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-S10AA	「BMW S1000RR」	2020	190
		TOTAL	190