

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5032	DATE	Oct. 22. 2021
MANUFACTURER	Trantechs, Ltd.		
DESCRIPTION OF DEFECT	In the vertical fire extinguisher box installed between the wheelbases of large and medium sized trucks, some have been fitted with improper hinge pins. For that reason, the pin may fall out due to vibrations during running, in the worst cases, the lid of the fire extinguisher box has fallen off, which may interfere with other traffic.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-FW1AHG 2RG-FW1AHG 2RG-FW1AHJ	HINO Profia	2020~2021	18	
2PG-FW1AJG		2020	1	
2PG-FW1EHG		2021	1	
2RG-FR1AHG 2SG-FR1AHH 2PG-FR1AHG		2020~2021	16	
2PG-FR1EHG		2020~2021	3	
2PG-FN1AGG		2020~2021	4	
2KG-FS1EHG		2021	1	
2KG-FC2ABA		HINO Ranger	2020~2021	2
2KG-FD2ABA 2KG-FD2ABG			2020~2021	3
2PG-FE2ABG			2020~2021	7
2KG-FJ2ABA	2020		1	
2KG-XZU710M 2RG-XZU710M	HINO Dutro		2020~2021	3
2KG-XZU775M		2020	1	
2SG-XKU712M		2021	2	
2RG-FRR90T2	Forward	2020	1	
2RG-FTR90V2		2020	1	
2PG-FS75HZ	FUSO Super Great	2020	1	
2PG-CD5CAVH	Quon	2020	2	
TOTAL			68	